



## Nickel/Acrylic conductive Coating

Nickel Acrylic Paint, cost effective, also available in aerosol for prototype and small runs.

### **Safety Precautions**

Harmful by inhalation – do not breathe vapour if not enough ventilation, wear respiratory equipment avoid contact with skin and eyes, keep away from sources of ignition – no smoking.

### **Emergency action**

#### **Spillage**

Absorb in earth or sand. Dispose in a safe way as for flammable solid.  
Prevent liquid entering sewers, basements and work pits: vapour may create explosive atmosphere. If substance has entered a water course or sewer or contamina.

#### **Fire**

Use water spray to cool containers. Extinguish with dry chemical, foam, CO2 or Sand.  
Do not use Waterjet.

#### **First Aid**

Remove contaminated clothing immediately. Wash affected skin with soap and water.  
If substance has got into eyes – immediately wash out with plenty of water for at least 15 minutes.  
In case of skin contact – wash with soap and water.  
For excessive vapour inhalation – remove to fresh air and seek medical attention.-.Do not use Waterjet.